



Doc. No.: STPL/RF/05/spl

Page 1 of 1

Ref: STPL/Tiles/JO – 293/12/ 2021.3

Test Order dated: 18.12.2021

Date: 31.12.2021

M/s. Sinter Machines  
# 35, Peelamedu Industrial Estate,  
V K Road, Peelamedu, Coimbatore  
Tamilnadu – 641 004

### REPORT ON ROOF TILE SAMPLE

Source of sample : Sample supplied by the customer  
Date of receipt of sample : 15.12.2021  
Customer's Reference : E mail dated 21.12.2021  
Period of Test : 27.12.2021  
Product Description# : Roof Tile – FR 1, FR 2, FR 3  
Condition of samples : Satisfactory

Sl. No.	Test Conducted	Test Method	Test Result
1	Fire Resistance – Spread of Flame	Lit fire on top surface of the tile and observation made	No spread of flame observed & No color change observed
2			No spread of flame observed & No color change observed
3			No spread of flame observed & No color change observed

# As furnished by the customer

- Note:
1. The results relate only to the items tested.
  2. Report shall not be reproduced, except in full, without the written approval of the lab.
  3. Any correction invalidates this report.

for STEDRANT TECHNOCLINIC PVT. LTD.

*Radhakrishna*  
31/12/2021  
 **Radhakrishna**  
Manager-Lab